

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**




FIG. 1




FIG. 2

300 →

385 →
390 →

395 →

Asset Management Maintenance

305 →

310 →

315 →

320 →

325 →

330 →

335 →

340 →

345 →

350 →

360 →

370 →

375 →


380 →

Devices

Email Settings

Return to Home

DEVICE DESCRIPTION:	Engine Driven Air Compressor
DEVICE LOCATION:	Power Building: Section B: Row 1
Date of Last Maintenance:	9-3-2003
Current Mechanical Condition :	MAINTENANCE DUE

330 → 

335 → EQUIPMENT LOAD:

On Time Duration:	953 hours
Total Cycles completed since last maintenance :	1732293
Total lifetime Cycles completed:	17152666

355 → FUEL CONSUMPTION:

Fuel Consumption:	123 therms/Day	NORMAL
-------------------	----------------	--------

365 → PERFORMANCE:

Average Horsepower:	109 HP	EXCESS
Average RPM:	325	NORMAL
Efficiency rating:	84%	

FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8